

HASTINGS MALLORY ELEMENTARY SCHOOL

BOTTLE #	LOCATION	SAMPLE ID	ANALYSIS	NYSDOH ACTION LEVEL	RESULTS
15	HME sink faucet room 20	HSF20	LEAD	5 ug/l	1.4 ug/l