

HASTINGS MALLORY ELEMENTARY SCHOOL

BOTTLE #	LOCATION	SAMPLE ID	ANALYSIS	NYSDOH ACTION LEVEL	RESULTS
10	HME sink faucet room 14	HSF14	LEAD	5 ug/l	3.4 ug/l
15	HME sink faucet room 20	HSF20	LEAD	5 ug/l	5.7 ug/l
28	HME sink faucet room 43	HSF43	LEAD	5 ug/l	3.2 ug/l